

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

| Representativ | es Present | During the Inspection: | |
|---------------|------------|-----------------------------|--|
| Company | Guy Davis | Environmental Scientist | |
| OGM | Pete Hess | Environmental Scientist III | |
| | | | |

Inspection Report

| Permit Number: | C0150009 |
|------------------|---------------------------|
| Inspection Type: | COMPLETE |
| Inspection Date: | Monday, November 26, 2007 |
| Start Date/Time: | 11/26/2007 9:52:00 AM |
| End Date/Time: | 11/26/2007 12:25:00 PM |
| Last Inspection: | Thursday, August 16, 2007 |

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Clear, crisp; 30's to 40's F.</u> InspectionID Report Number: <u>1471</u>

Accepted by: dhaddock

12/5/2007

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: TRAIL MOUNTAIN MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

✓ Underground

Surface

Loadout

Processing

Reprocessing

| 3,539.00 | Total Permitted | ✓ | Fed |
|----------|------------------------|----------------|-------|
| 10.69 | Total Disturbed | $ \mathbf{Z} $ | State |
| | Phase I | | Cou |
| | Phase II | f — | Fee |
| | Phase III | | Other |

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the required quarterly electronic submittal of surface and ground water monitoring information. Third quarter 2007 water data is currently being entered into the Division data base pipeline. The permittee continues to meet the Special Permit Condition included as Attachment "A" of the current State permit. This site remains in temporary cessation status.

There are no pending compliance actions for the Trail Mountain Mine permit area.

Inspector's Signature:

Date

Monday, November 26, 2007

Pete Hess, Environmental Scientist III
Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150009 Inspection Type: COMPLETE

Inspection Date: Monday, November 26, 2007

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcemen |
|------|---|-----------|----------------|----------|------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | ✓ | | | |
| 2. | Signs and Markers | ✓ | | | |
| 3. | Topsoil | V | | | |
| 4.a | Hydrologic Balance: Diversions | V | | V | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | ✓ | | V | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | ✓ | | ✓ | |
| 4.d | Hydrologic Balance: Water Monitoring | ✓ | | V | |
| 4.e | Hydrologic Balance: Effluent Limitations | ✓ | | ✓ | |
| 5. | Explosives | V | | ✓ | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | ✓ | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | | V | | |
| 8. | Noncoal Waste | ✓ | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | V | | V | |
| 10. | Slides and Other Damage | ✓ | | ✓ | |
| 11. | Contemporaneous Reclamation | | ✓ | | |
| 12. | Backfilling And Grading | | ✓ | | |
| 13. | Revegetation | | V | | |
| 14. | Subsidence Control | ✓ | | | |
| 15. | Cessation of Operations | ✓ | | | |
| 16.a | Roads: Construction, Maintenance, Surfacing | ✓ | | | |
| 16.b | Roads: Drainage Controls | ✓ | | | |
| 17. | Other Transportation Facilities | ✓ | | | |
| 18. | Support Facilities, Utility Installations | ✓ | | | |
| 19. | AVS Check | ✓ | | | |
| 20. | Air Quality Permit | ✓ | | V | |
| 21. | Bonding and Insurance | ✓ | | ✓ | |
| 22. | Other | | | | |

Permit Number: C0150009 Inspection Type: COMPLETE

Inspection Date: Monday, November 26, 2007

Page 3 of 4

4.a Hydrologic Balance: Diversions

The Permittee has redefined the temporary diversion berms which have been installed across the pad area down gradient of the fuel storage area. These berms were implemented to reduce the intercepted flow volume which had previously reported across the pad thence into the sediment pond. The berms re-direct the flow volume into the concrete ditch which parallels the disturbed area fence and divide the total volume into smaller quantities which in turn reduces the erosive affect on the slope above the sediment pond. All other diversions were capable of functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The third quarter 2007 impoundment inspection for the Mine site sediment pond was conducted by Messrs. John Christensen and Rick Cullum on September 10, 2007. There were no signs of instability or other structural hazards noted. The pond was reported as having 0.122 acre feet of sediment storage capacity remaining prior to reaching the 60% sediment cleanout elevation. As observed this day, the pond contained a small amount of water, which was frozen. The professional engineer and registered land surveyor certifications were performed for the September 10 inspection on October 31, 2007. There were no compliance issues noted with the pond during todays inspection by the Division.

4.c Hydrologic Balance: Other Sediment Control Measures

A new silt fence has been installed along the toe of the topsoil pile which is located behind the concrete fan ducting.

4.d Hydrologic Balance: Water Monitoring

Discharge monitoring reports for the two permitted UPDES outfalls were reviewed for the month of October. Neither 001A nor 002A had flows. The reporting forms were submitted by the Permittee to the appropriate government agencies on November 14, 2007.

4.e Hydrologic Balance: Effluent Limitations

The Permittee notified the Utah Division of Water Quality on October 4, 2007 that Mr. Earl Snow, Mine Manager of the Deer Creek Mine, would be the person responsible for signing all discharge monitoring reports for all of the outfalls permitted under the various Energy West UPDES permits.

5. Explosives

The Permittee recently completed a hazardous material inventory for Corporate which included information relative to explosive and detonator storage at the central warehouse. There are no explosives in storage at the Trail Mountain site.

Permit Number: C0150009
Inspection Type: COMPLETE

Inspection Date: Monday, November 26, 2007

Page 4 of 4

9. Protection of Fish, Wildlife and Related Environmental Issues

The chain link fencing which was installed to prevent unauthorized access into the sealed Mine entries remains intact.

10. Slides and Other Damage

The shot crete slope adjacent to the ventilation fan motor room remains unchanged.

20. Air Quality Permit

There is no activity occurring at this site.

21. Bonding and Insurance

The general liability insurance coverage for this site has been renewed and remains in effect until August 28, 2008. Coverage amounts for general liability and each occurrence are listed at \$ 2,000,000 for each category. Coverage for damage from the use of explosives is provided. The cancellation clause meets the requirements of the R645 Coal Mining Rules.